: STEP (CASTING DETAIL)

Thursday, 11/16/2006 4:25:26 PM

User:

Kim Johnston

**Process Sheet** 

Customer

: CU-DAR001 Dart Helicopters Services

Job Number : 29486

**Estimate Number** 

: 10510

P.O. Number This Issue

: NIA : 11/16/2006

: NC

: N/A : 23060

S.O. No. : NIFE

Type

: PURCHASED PARTS

**Part Number Drawing Number** 

**Drawing Name** 

: D2576 REV. E1 : N/A

**Project Number Drawing Revision** 

: D25763

Material **Due Date** : 10/5/2006

Qty:

Each

Written By

Prsht Rev.

First Issue

Previous Run

Checked & Approved By

Comment

: Est: E 02.08.19

Consolidated D2576-1 and D2576-3

KJ/RF

**Additional Product** 

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

1.0

D25761

Step (Casting Detail)



Comment: Qty.:

1.0000 Each(s)/Unit

Total:

100.0000 Each(s)

Pick:

Qty

Part#

Description

D2576-1 Step (Casting Detail)

2.0 HAAS1

HAAS CNC VERTICAL MACHINING #1



Comment: HAAS1

1- Machine as per Folio FA332 and Dwg D2576

2- Deburr

MS

3.0

QC2

Comment: INSPECT PARTS AS THEY COME OFF MACHINE

4.0

QC8

SECOND CHECK

Comment: SECOND CHECK

5.0

**PACKAGING 1** 

PACKAGING RESOURCE #1

Comment: PACKAGING RESOURCE #1

Identify and Stock Location:

E 06/12/11

## **Dart Aerospace Ltd**

W/O: WORK ORDER CHANGES						**************************************		
DATE STEP		PROCEDURE CHANGE			Date	Date Qty		Approval QC Inspector
			*					

Part No: Da576-3 PAR #: NA Fault Category: Ped Machine Protock No. DQA: NO DQA: Date: Ob. 12.12

NCR:	29486	W	ORK OR	DER NON-CONFORMANC	E (NCR)	•		
		Description of NC		Corrective Action Section B	Verification	Approval	Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
0412/03	2	the pocket ,063" deep	B	Scripp: clestray.	びた	/-/	B	
		is to thin.	SIRI	4	06/12/01	10.12.n	can	20:12.11
				NO-KeplAce				
. \.a	2	- ) part came out of jig while machining	18	No-Leplace Scrap : destroy	IL		B	1
10/E/166		- 1 part . 063 pocket is too	OF B	,	delialog	10.12.12	OSTIN	06.12.11
		deep		No replace,				001211

NOTE: Date & initial all entries

Date: User:

Thursday, 11/16/2006 4:25:26 PM

Kim Johnston

**Process Sheet** 

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: STEP (CASTING DETAIL)

Job Number: 29486

Part Number: D25763

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

6.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE



06/12/12

Job Completion



U &e. 17. 1

## **Dart Aerospace Ltd**

DuitAo	Part Acrospace Eta									
W/O:		WORK ORDER CH	IANGES							
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
					-					
		· ·								
Part No	:	PAR #: Fault Category:	NCR: Yes	No DQ	A:	_ Date: _				
			QA:	N/C Close	d:	_ Date: _	······			
NCR:		WORK ORDER NON-CONFO	ORMANCE (NC	R)						

NCR:			WORK ORDE	ER NON-CONFORMAN	CE (NCR)			
		Description of NC		Corrective Action Section B				Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	QC Inspector
				•				
								-

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order:	29486
Description: Step	Part Number:	D2576-3
Inspection Dwg: D2576 Rev: E1		Page 1 of 1

## FIRST ARTICLE INSPECTION CHECKLIST

	LIKOI	AKTICLE	NOFECTI	ON CHE	CKLIST	
	X	First Arti	cle	Prot	otype	
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
7.05	+/-0.030	7.072"				
Ø0.50	+/-0.030	495"	\\frac{1}{2}			
Slot 0.250 x 0.65	+/-0.030	,254x,65				
Slot 0.250 x 1.28	+/-0.030	, 254 11,25	3 /			
	, "					·
			-			
		·				

Measured by:	Audited by:	12	Prototype Approval:	N/A
Date: 06/12/07	Date:	06.12.09	Date:	N/A

Rev	Date	Change	Revised by	Approved
Α	04.02.10	New Issue	KJ/RF	14

